




**Issue Date:** March 19, 2014

**SB Number:** SB27A

**Topic:** Temperature Sensor Replacement on CEN Temperature-Voltage Sense Harnesses With or Without Other External Connections such as J1939 Connectors

When troubleshooting the CEN temperature-voltage sense harnesses, the harness may prove defective either at the temperature sensor or in the entire harness.

If the temperature sensor in the B- terminal black wire is proven defective, the sensor and terminal assembly can be replaced with the A9-4056 temperature sensor terminal assembly. Contact your CEN Factory-Authorized Service Dealer or CEN Aftermarket Group for further information.



The entire temperature-voltage sense harness can also be replaced as an alternative to replacing just the sensor assembly. Contact your CEN Factory-Authorized Service Dealer or CEN Aftermarket Group for further information.

Please file this CEN Service Bulletin with your CEN Literature. Please forward to the appropriate people in your company.